

# Wiha screw extractor.

## Screw extractor



### 405 11 Screw extractor set with spiral drill bit, 16 pcs.

Material: Screw extractor of tough-yet-flexible chrome-vanadium-molybdenum steel, through-hardened, bronzed.

HSS spiral drill bit, blank.

Application: For thread-conserving removal of damaged or broken-off screws with left-hand or right-hand thread, particularly stripped hex screws. Simply hammer in the extractor, position the ring spanner to the bottom and screw out without tilting.

Order-No.	Series				
03988	405 11				1
●	405	2.0x85	2.5x85	3.0x85	4x85
		5x85	6x95	8x95	10x110
⊗		2.3x53	2.8x51	3.4x70	4.5x80
		5.7x93	6.8x109	9.0x117	11.0x142



### NEW

### 405 Screw extractor

Material: Tough-yet-flexible chrome-vanadium molybdenum steel, through-hardened, bronzed.

Application: For thread-conserving removal of damaged or broken-off screws with left-hand or right-hand thread, particularly a stripped hex screw. Simply hammer in the extractor, position the ring spanner to the bottom and screw out without tilting.

Order-No.	●	↔	⊗	
03847	2.0	85	6.0	1
03848	2.5	85	6.0	1
03849	3.0	85	7.0	1
03850	4	85	8.0	1
03851	5	85	8.0	1
03852	6	95	8.0	1
03853	8	95	10.0	1
03854	10	110	12.0	1

## Wiha Info


### Screw extractor

1 a



Damaged or rounded hex screw caps or...

2 a




...broken-off screw head

2 b




Pre-drill with spiral drill bit

1 b




Firmly hammer in the screw extractor with a hammer

2 c



1 c



Slide in the ring spanner to the bottom and screw out without tilting

2 d

