

1 Products affected

Product hierarchy no. *			Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PGU	Type			
01	001	007	0000000032	See list below	Circuit Protection	SPT 6.3x32 10-32A

*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)

List of part numbers affected						
0001.2534	0001.2535	0001.2536	0001.2537	0001.2538	0001.2539	


2 Type of change

Material change. Soldering method change.

3 Detailed description of change

The tube material changed to ceramic.

Fuse element is now soldered internally to ferrules. Used to be soldered externally.



4 Reason of change

Product improvement

5 Released date

This change is valid from 1.2.2015

6 Impact of change and recommended action

Form:	Yes	Tube material changed to ceramic
Fit:	No	No dimensional change
Function:	No	No functional change
Production Site:	No	Production site remains

7 Reference Documents / Attachments

Kind of document	Document number	Remarks
Link to Web Datasheet		SPT_6.3x32

SPT 6.3x32					
creation date	created by	release date	released by	notification no.	revision
11.2.2015	SHÖ	17.2.2015	SHÖ	xxx	1 von 1