


## 8667-9/Z TORX® Bit-Check – Rapidaporter



1 Universal bit holder Rapidaporter 888/4/1 K with quick-release chuck suitable for power tools and electronic drills

Code			
05057115001	●○ 888/4/1 K	1 x 1/4"x50	10
	● 867/1 Z TORX®	1 x TX 6x25; 1 x TX 8x25; 1 x TX 9x25; 1 x TX 10x25; 1 x TX 15x25; 1 x TX 20x25; 1 x TX 25x25; 1 x TX 30x25; 1 x TX 40x25	

## 8800-9/TZ Bit-Check – Rapidaporter with ringmagnet



1 Universal bit holder Rapidaporter 887/4 RR with ringmagnet and quick-release chuck suitable for power tools and electronic drills

Code			
05056378001	●○ 887/4 RR	1 x 1/4"x57	10
	● 800/1 TZ	1 x 0,8x5,5x25; 1 x 1,0x5,5x25; 1 x 1,2x6,5x25	
	● 851/1 TZ PH	1 x PH 1x25; 1 x PH 2x25; 1 x PH 3x25	
	● 855/1 TZ PZ	1 x PZ 1x25; 1 x PZ 2x25; 1 x PZ 3x25	



### How to tighten screws without holding them



The floating, free-turning magnetic sleeve securely holds even large and heavy screws to enable immediate application. There is no need to hold the screw when applying the tool – something which can be dangerous and painful. Also ideal for overhead work.

## 8855-9/TH Bit-Check – Rapidaporter with ringmagnet



1 Universal bit holder Rapidaporter 887/4 RR with ringmagnet and quick-release chuck suitable for power tools and electronic drills

Code			
05056379001	●○ 887/4 RR	1 x 1/4"x57	10
	● 855/1 TH PZ	3 x PZ 1x25; 3 x PZ 2x25; 3 x PZ 3x25	

## 8855/67-9 Bit-Check – Rapidaporter with ringmagnet



1 Universal bit holder Rapidaporter 887/4 RR with ringmagnet and quick-release chuck suitable for power tools and electronic drills

Code			
05056388001	●○ 887/4 RR	1 x 1/4"x57	10
	● 855/1 TH PZ	1 x PZ 1x25; 2 x PZ 2x25	
	● 867/1 TZ TORX®	1 x TX 10x25; 1 x TX 15x25; 1 x TX 20x25; 1 x TX 25x25; 1 x TX 30x25; 1 x TX 40x25	

