

Accessories & Production Aids



CT-1

 CROWN® lead-free tip tinner and cleaner to maintain your Edsyn CROWN® tips or any heavy duty tips (1.5 oz. or 42.5g)



WP286

- WIGAPRY® desoldering aid
- Use to straighten pins or leads and remove circuit devices



WP556

• WIGAPRY® mini screwdriver and calibration aid tool



ST800

 SMD helper helps remove surface mount devices while using soldering or hot air tools



ST706

 SMD helper helps lift and remove surface mount devices while using hot air tools (.002 shim, .238 width)



LT-1

 LONER_® lead -free tip tinner and cleaner to maintain your Edsyn LONER_® soldering tips (.5 oz or 14.2g)



RB641

 SMD shim blade replacement with staticsafe spool holder to be used with ST706 or ST800 SMD helpers



WS630

 SMD pull wire replacement and static-safe spool holder to be used with ST706 or ST800 SMD helpers [Dia: .01 in. (.25 mm) L: 10 ft (3.05 m)]



TC383

 K-Type thermocouple and subminiature connector assembly with ZD13 desoldering tip and RS383 retaining sleeve attached (use as a calibration aid with MS412 temperature measuring system)



WT618

• Dual ended wrench for removing hot air tips (set of 2)



WT619

 Tip wrench for removing desoldering tips using RS383 retaining sleeve (comes with UC274 clamp for attaching to station for easy access)



WT620

 Socket wrench for removing smaller hot air tips that use RN432 and RN433 retaining nuts



OL111

• O-Ring lube for lubrication and longer tool life



MS412

 Compact digital meter system suitable for measuring and calibrating soldering or desoldering tip temperatures. Displays in C° and F°.

Note: This section is limited. For a complete list ask for Edsyn's Hand Tools Catalog solely dedicated to production aids and accessories.

www.edsyn.com













