

Identification	Part number	Drawing	Dimensions in mm
<b>HARTING Crimping tool</b> for F.O. connector (glass fibre) SW 4.3 mm SW 3.8 mm SW 4.95 mm	20 99 000 1031	 For crimping the strain relief to the connector F.O. cable for glass fibre	
<b>HARTING Crimping tool</b> for F.O. connector (POF <sup>1)</sup> fibre) SW 6.95 mm SW 4.95 mm SW 3.0 mm	20 99 000 1033	 For crimping the strain relief to the connector F.O. cable for POF <sup>1)</sup> fibre	
<b>Vierkerbcrimpzange</b> for following 1 mm POF <sup>1)</sup> contacts Han D <sup>®</sup> , Han E <sup>®</sup> DIN 41 626 Ferrule F-SMA, -ST	20 99 000 1035	 This tool is only usable for F.O. contacts. Crimping tools for electrical contacts see catalogue "Industrial Connectors Han <sup>®</sup> ".	
<b>Crimping tool Han-Brid<sup>®</sup></b> for electrical and optical crimp contacts	09 99 000 0362		
<b>Cutting tool</b> 2.2 mm POF <sup>1)</sup>	20 99 000 1049	Delivery range 10 pieces / set	
<b>Fibre stripper</b> 1 mm POF <sup>1)</sup>	0.3 mm <b>20 99 000 1041</b> 1 mm <b>20 99 000 1045</b> 0.18 / 0.3 mm <b>20 99 000 1046</b>		