

# Linear stepper motor UBL

## Linearschrittmotor UBL

### Moteur pas-à-pas linéaire UBL

#### Order Reference Complement

##### Order Reference

Type	Stepper Motor	UBL	13	N	100	B	3C
Configuration	13 bipolar 23 unipolar						
Approval	N Approval Standard						
Resistance	See next page Resistance per winding for bipolar or unipolar.						
Connection	Jack connector 6 pin (other on request)						
Shaft	3C Travel 8 mm ± 0,7 mm / Tr. 3,7 x 1 (other on request)						

#### Travel Encoding

**3C** Travel 8 mm

**1E** Travel 13 mm

**1M** Travel 56 mm